

Topic :- Electro Magnetic Induction

1 (b)

$$\frac{L_B}{L_A} = \left(\frac{n_B}{n_A}\right)^2 \Rightarrow L_B = \left(\frac{500}{600}\right)^2 \Rightarrow 108 = 75 \text{ mH}$$

2 (a)

Though emf is induced in the copper ring, but there is no induced current because of cut in the ring. Hence nothing opposes the free fall of the magnet. Therefore,
 $a = g$.

3 (b)

Power $P = \frac{e^2}{R}$; hence $e = -\left(\frac{d\phi}{dt}\right)$ where $\phi = NBA$

$$\therefore e = -NA\left(\frac{dB}{dt}\right). \text{ Also } R \propto \frac{1}{r^2}$$

Where $R =$ resistance, $r =$ radius, $l =$ length

$$\therefore P \propto \frac{N^2 r^2}{l} \Rightarrow \frac{P_1}{P_2} = 1$$

4 (a)

$$\frac{N_s}{N_p} = \frac{V_s}{V_p} \Rightarrow \frac{250}{100} = \frac{V_s}{28/\sqrt{2}} \Rightarrow V_s = 50 \text{ V}$$

5 (d)

$$e = Bl^2\pi v = 0.4 \times 10^{-4} \times (0.5)^2 \times (3.14) \times \frac{120}{60} \\ = 6.28 \times 10^{-5} \text{ V}$$

6 (b)

As x increases so $\frac{dB}{dt}$ increases, i.e., induced emf (e) is negative. When loop completely enters in the magnetic field, $\text{emf} = 0$

When it exists, x increases but $\frac{dB}{dt}$ decreases, i.e., e is positive

7 (b)

$$U = \frac{1}{2} Li^2, \text{ i.e., } \frac{U_2}{U_1} = \left(\frac{i_2}{i_1}\right)^2 = \left(\frac{1}{2}\right)^2 = \frac{1}{4} \Rightarrow U_2 = \frac{1}{4} U_1$$

8

(c)Given, $L = 10\text{H}$, $f = 50\text{ Hz}$

For maximum power

$$X_C = X_L$$

$$\frac{1}{\omega C} = \omega L$$

$$C = \frac{1}{\omega^2 L}$$

$$\therefore C = \frac{1}{4\pi^2 \times 50 \times 50 \times 10}$$

$$C = 0.1 \times 10^{-5}\text{F} = 1 \mu\text{F}$$

9

(c)

$$\eta = \frac{e}{E} \times 100 \Rightarrow e = 0.3 E$$

$$\text{Now, } i = \frac{E - e}{R} \Rightarrow 12 = \frac{50 - (0.3 \times 50)}{R} \Rightarrow R = 2.9\Omega$$

90

(c)

Total charge induced in a loop depends on resistance and change in magnetic flux linked with the loop.

11

(b)

In transformer

$$\frac{n_p}{n_s} = \frac{V_p}{V_s}$$

$$= \frac{5000}{240} = 20.8$$

12

(b)

If resistance is constant (10Ω) then steady current in the circuit $i = \frac{5}{10} = 0.5\text{ A}$. But resistance is increasing it means current through the circuit starts decreasing. Hence inductance comes in picture which induces a current in the circuit in the same direction of main current. So $i > 0.5\text{ A}$

13

(b)

$$e \propto \omega$$

14

(c)

$$\frac{N_s}{N_p} = \frac{V_s}{V_p} \Rightarrow \frac{1}{20} = \frac{V}{2400} \Rightarrow V_s = 120\text{ V}$$

$$\text{For } 100\% \text{ efficiency } V_s i_s = V_p i_p$$

$$\Rightarrow 120 \times 80 = 2400 i_p \Rightarrow i_p = 4\text{ A}$$

15

(d)

$$\text{From, Faraday's second law, } e = -\frac{d\phi}{dt}$$

$$= -[12t - 5]$$

$$= -[12 \times (0.25) - 5] = +2$$

$$\text{Now, } i = \frac{e}{R} = \frac{2}{20} = 0.1\text{ A}$$

16 **(d)**

Efficiency of a transformer,

$$\eta = \frac{\text{Power output}}{\text{Power input}}$$

For an ideal transformer, $\eta = 1$

$$\therefore \text{Power output} = \text{Power input} = 60 \text{ W}$$

18 **(b)**

$$\begin{aligned} \text{Induced e.m.f.} &= Blv = 0.3 \times 10^{-4} \times 10 \times 5 \\ &= 1.5 \times 10^{-3} \text{ V} = 1.5 \text{ mV} \end{aligned}$$

19 **(b)**

Magnetic flux, $\phi = \int \mathbf{B} \cdot d\mathbf{A} = BA \cos \theta$, where θ is angle between normal to the area dA with magnetic field B .

$$\text{Here, } \theta = (90^\circ - 30^\circ) = 60^\circ$$

$$\begin{aligned} \text{and } \theta &= 10^{-4} \times \pi \left[\frac{21}{2} \times 10^{-2} \right]^2 \times \cos 60^\circ \\ &= 1.732 \times 10^{-6} \text{ Wb} \end{aligned}$$

20 **(c)**

Current in B_1 will promptly become zero while current in B_2 will slowly tend to zero

PE

ANSWER-KEY										
Q.	1	2	3	4	5	6	7	8	9	10
A.	B	A	B	A	D	B	B	C	C	C
Q.	11	12	13	14	15	16	17	18	19	20
A.	B	B	B	C	D	D	D	B	B	C

PE